



## SAFE WORK PRACTICE

<b>TITLE</b>	Clearing A/O Grading Of Pipeline Right Of Way
<b>GENERAL</b>	Protecting workers from injuries associated with clearing and grading operations
<b>APPLICATION</b>	In order to make the right-of-way a suitable work area, the removal of trees, brush and other vegetation is required.
<b>PROTECTIVE MECHANISMS</b>	Safe work procedure Permit system PPE Barricades and warning signs Manufacturers specifications Equipment maintenance procedures ERP (Emergency Response Plan)
<b>SELECTION AND USE</b>	As per safe work procedure Manufacturers specifications
<b>FOREMANS RESPONSIBILITY</b>	Foremen are responsible to facilitate and/or provide proper instruction to their workers on protection requirements and training Hazard assessment Work site inspection
<b>WORKER RESPONSIBILITY</b>	<ol style="list-style-type: none"> <li>1. Inspect equipment prior to use (walk around).</li> <li>2. Stay within an operator's vision.</li> <li>3. Be aware of power line proximity.</li> <li>4. Watch for falling objects.</li> <li>5. Use care and caution when using chain saws.</li> <li>6. Use recommended ointments and repellents.</li> <li>7. Do not ride on equipment unless appropriate seating is available.</li> <li>8. Do not stand between winch and object being moved.</li> <li>9. Do not leave equipment running while adjusting or fuelling.</li> </ol>