



Mounting - Dismounting Equipment

Developed by:		Approved by:	Date created:	Last revision:
Jason M. Moffatt		G. Kaluzniak	January , 2016	December 1, 2022
Possible Hazards Present		Personal Protection Required		Additional Training
<ul style="list-style-type: none"> - Slip/Trip hazard - Fall injury - Pinch points 		<ul style="list-style-type: none"> - CSA Footwear - Hard Hat - Safety Vest 		- PPE
<ol style="list-style-type: none"> 1. Clean boots of mud or ice before climbing into machine or truck. 2. Using grab rail and facing the machine/truck, step onto the first step. 3. Maintain 3-point contact always (two hands and one foot, or one hand and two feet) 4. Climb into cab. 5. To climb off machine/truck, make sure the machine is on level ground and brakes are set. 6. Step out of cab onto ladder and while facing the machine descend using the 3- point method. 7. Do not jump from the machine/truck or get off while it is in motion. 8. Be extra cautious under wet or icy conditions. 9. Do not allow anyone to ride outside of machines/trucks. 				
<p>Documentation/Legislation Workplace Safety and Health Regulation, M.R. 217/2006 Part 4 - General Workplace Requirements Part 6 - Personal Protective Equipment Part 16 - Machines, Tools, & Robots Part 22 - Powered Mobile Equipment</p>			<p>This Safe Work Procedure will be reviewed anytime the task, equipment or materials change and at a minimum every three years.</p>	