



SAFE WORK PRACTICE

TITLE	Plasma Cutter
GENERAL	Protecting workers involved with Plasma cutting operations
APPLICATION	Plasma cutters are frequently used for cutting metals
PROTECTIVE MECHANISMS	Safe Work Procedure Safety Goggles Gloves Proper fitting clothes to prevent catching sparks, fire retardant preferred
SELECTION AND USE	As per job procedure Manufacture recommendations
SUPERVISOR RESPONSIBILITY	Supervisors are responsible to provide proper instruction on protection requirements, and safe operation.
WORKER RESPONSIBILITY	<ol style="list-style-type: none">1. Ensure you have received proper training instructions.2. Ensure proper use of PPE.3. Follow proper housekeeping, and check equipment before each use.4. Ensure the safety of all co-workers within workspace.